



U.S. Environmental Protection Agency
Region 5 - Air and Radiation Division

Correspondence



March 6, 2003

(A-18J)

Janet McCabe, Assistant Commissioner
Office of Air Quality
Indiana Department of Environmental Management
100 North Senate Avenue
P.O. Box 6015
Indianapolis, Indiana 46206-6015

Robert F. Hodanbosi, Chief
Division of Air Pollution Control
Ohio Environmental Protection Agency
122 South Front Street
P.O. Box 1049
Columbus, Ohio 43266-1049

Dave Kolaz, Chief
Bureau of Air
Illinois Environmental Protection Agency
1021 North Grand Avenue East
Springfield, Illinois 62702

James Warner, Director
Majors and Remediation Division
Minnesota Pollution Control Agency
520 Lafayette Road N.
Saint Paul, MN 55155-4194

G. Vinson Hellwig, Chief
Air Quality Division
Michigan Department of Environmental Quality
Constitution Hall, 525 West Allegan Street
P.O. Box 30260
Lansing, Michigan 48909

Lloyd Eagan, Director
Bureau of Air Management
Wisconsin Department of Natural Resources
101 South Webster Street

P.O. Box 7921
Madison, Wisconsin 53707

Dear Ms. McCabe:

In discussions with United States Environmental Protection Agency (EPA) Region 5, State permitting authorities have requested clarification on our fugitive emissions policy. Specifically, the States have asked EPA to clarify to what extent, and from which emission units, are fugitive emissions counted towards major source applicability for Title V, nonattainment new source review (NSR), and prevention of significant deterioration (PSD). Various EPA letters and memoranda provide guidance on when you count fugitive emissions to determine whether a source is a major stationary source subject to Title V, NSR, or PSD, but there is no one guidance document which addresses the various scenarios which arise.

In the enclosed analysis, we are providing some examples that should help you understand when to include fugitive emissions in determining whether a source is major for purposes of Title V, NSR, or PSD. However, no part of this document, including the following examples, create any new legally binding obligations. Rather, the purpose of this document is to help you understand the statutory provisions and regulations which govern when fugitive emissions are included in major source determinations and EPA's interpretation of these provisions and regulations.

This response has been coordinated with staff in EPA's Office of Air Quality Planning and Standards, Office of Enforcement and Compliance Assurance, and Office of General Counsel in order to help assure completeness and accuracy.

If you have any questions regarding this letter, please contact Sam Portanova, of my staff, at (312) 886-3189.

Sincerely yours,

/s/ (Stephen Rothblatt for)

Cheryl L. Newton, Acting Director
Air and Radiation Division

Enclosure

ANALYSIS

What Effect Did the November 27, 2001, Title V Rulemaking Have on the Counting of Fugitive Emissions?

On November 27, 2001 (66 FR 59161), EPA published a rule, "Change to Definition of Major Source," that requires or clarifies the following

for Title V:

- An owner or operator of a source must include the fugitive emissions of all pollutants regulated under the Clean Air Act in determining whether the source is a major stationary source under Title V if the source falls within one of the source categories listed through a rulemaking pursuant to section 302(j) of the Act ("listed source categories").¹ Included as listed source categories are source categories regulated by a section 111 or 112 standard on or before August 7, 1980.
- An owner or operator of a source that falls within a listed source category that was regulated by a section 111 or 112 standard on or before August 7, 1980, must include the fugitive emissions of all air pollutants regulated under the Act, not just those pollutants regulated by the section 111 or 112 standard, in determining whether the source is a major stationary source under Title V.
- An owner or operator of a source must include the fugitive emissions of all hazardous air pollutants ("HAPs") listed under section 112(b) of the Act in determining whether the source is a major source for purposes of section 112 and Title V, regardless of whether the source falls within a listed source category. See National Mining Ass'n v. EPA, 59 F.3d 1351 (D.C. Cir. 1995).

What Are Some Examples of When You Count Fugitive Emissions to Determine Whether Your Source is Major?

Below are several scenarios that illustrate how to consider fugitive emissions in determining whether a source is a major stationary source.² You should note that the examples below rely on certain assumptions regarding the complex industrial facilities described. The question of what is the primary activity at such a source or what emission units are properly considered to be a part of the source can be difficult to answer in any given case. The assumptions underlying these examples are not intended to shortcut the very fact intensive inquiry that such questions may require.

Scenarios

The first 3 scenarios below apply to the counting of fugitive emissions of regulated pollutants. The last scenario applies to the counting of fugitive emissions of any HAP listed under section 112(b) of the Act.

1. A stationary source in a listed source category. If the primary activity of a stationary source falls within a listed source category, then fugitive emissions are included from all emissions units at the source. The stationary source encompasses not only all

emission units within the same SIC code at the facility, but also emission units at support facilities that are part of the source.

Examples:

- A petroleum refinery. Petroleum refineries are a listed source category. You include fugitive emissions from the refinery to determine whether it is a major stationary source.

CA steel mill with an onsite slag handling operation. The primary activity of the source, in this case, is the production of steel, and steel mills are a listed source category. Although slag handling is not a listed source category, the onsite slag handling operation here is a support facility for the steel mill. You include fugitive emissions from the steel mill (a listed source category and the primary activity at this source) as well as the fugitive emissions from the slag handling operation (an unlisted source category, but one which supports the primary activity here) to determine if the source is a major stationary source.

CA fossil-fuel-fired steam electric plant of more than 250 million BTUs per hour heat input located a short distance away from a coal mine that supplies all of its coal to the steam electric plant. The primary activity of the source, in this case, is the generation of steam and electricity, and steam electric plants as described above are a listed source category. You include fugitive emissions from the steam electric plant (a listed source category and the primary activity at this source) as well as the fugitive emissions from the coal mine (an unlisted source category and the support facility at this source) to determine if the source is a major stationary source.

2. A stationary source in an unlisted source category. If the primary activity of a stationary source falls within a source category that is not listed, then as a general matter fugitive emissions from the emissions units at the source are not included in determining whether the source is a major stationary source. However, if the source also contains emission units which do fall within a listed source category (or categories), then you include fugitive emissions from these listed emissions units to determine if the source is a major stationary source.

Examples:

CA food processing plant that has several petroleum liquid storage tanks subject to the NSPS in 40 CFR part 60, subpart Ka. The primary activity of the source, in this case, is the processing of food, and food processing plants are not a listed source category. The storage tanks, however, fall within a listed source category as this source

category was regulated by subpart Ka as of August 7, 1980. You include fugitive emissions only from the storage tanks to determine if the source is a major stationary source.

CA coal mine with an onsite coal cleaning plant with a thermal dryer. The primary activity of the source, in this example, is the mining of coal, and coal mines are not a listed source category. The coal cleaning plant, however, does fall within a listed source category. You include fugitive emissions only from the coal cleaning plant to determine if the source is a major stationary source.

3. A stationary source in one of the source categories regulated by a section 111 new source performance standard (NSPS) on or before August 7, 1980, that contains emissions units that are grandfathered from the NSPS requirements (e.g., constructed before the applicability date of the NSPS) or that are not regulated as "affected facilities" under the NSPS. You include fugitive emissions from all emission units at the source to determine if it is a major stationary source because the source falls within a listed source category. The decision to include fugitive emissions from a stationary source is not influenced by whether specific emissions units are subject to regulation.

Examples:

CA grain elevator of the type covered by the NSPS in 40 CFR part 60, subpart DD, but which is grandfathered from the requirements of this NSPS. Since subpart DD was promulgated prior to August 7, 1980, the grain elevator falls within a listed source category. You include fugitive emissions from the grain elevator to determine if the source is a major stationary source.

CA coal prep plant of the type covered by the NSPS in 40 CFR part 60, subpart Y. The coal prep plant falls within a listed source category as this source category was regulated by subpart Y as of August 7, 1980. The coal prep plant includes emissions units that are not regulated as "affected facilities" under the NSPS. You include fugitive emissions from all emission units at the coal prep plant to determine if the source is a major stationary source, including fugitive emissions from the units that are not regulated as "affected facilities" under the NSPS.

4. A source which emits fugitive emissions of any HAP listed under section 112(b) of the Act.³ You include fugitive HAP emissions from all emissions units at a source to determine if the source is a major source without regard to whether the source falls within a listed source category. Although most emissions of HAPs are nonfugitive due to advancing technology, some likely emitters of fugitive HAPs as of the date of this letter are pumps, valves, compressors, or flanges

found at petroleum refineries, chemical processing plants, tank farms (i.e., facilities which have a collection of storage tanks), and crude oil and natural gas production facilities.

In reading this document, please remember that it is not a regulation and does not substitute for the applicable regulations. The Clean Air Act and EPA's regulations governing NSR, PSD, and Title V contain legally binding requirements. In contrast, the statements made in this document do not create legal rights or impose legally binding requirements on EPA, the States, or the regulated community. Rather, the purpose of this document, including the scenarios above, is to help you understand the statutory provisions and regulations which govern when fugitive emissions are included in major source determinations and EPA's interpretation of these provisions and regulations. It is important to note that any decisions regarding a particular facility will be made based on the statute and regulations.

This discussion of various possible scenarios is not exhaustive. In deciding whether to include fugitive emissions from a stationary source in determining major source applicability, you may find the following sources of information useful in addition to those mentioned above:

C "Requirements for Preparation, Adoption, and Submittal of Implementation Plans; Approval and Promulgation of Implementation Plans," 45 Fed. Reg. 52676, 52695 (August 7, 1980)

C "Requirements for Implementation Plans: Surface Coal Mines and Fugitive Emissions; Approval and Promulgation of Implementation Plans," 54 Fed. Reg. 48870, 48881-48882 (Nov. 28, 1989)

C "New Source Performance Standards (NSPS) - Applicability of Standards of Performance for Coal Preparation Plants to Coal Unloading Operations," 63 Fed. Reg. 53288, 53290 (October 5, 1998)

C Letter from Edward J. Lillis to Thomas C. O'Connor (Oct. 14, 1994) (<http://www.epa.gov/rgytgrnj/programs/artd/air/title5/t5memos/fugitive.pdf>)

C Letter from Robert G. Kellam to Donald P. Gabrielson (March 1, 1996) (<http://www.epa.gov/rgytgrnj/programs/artd/air/title5/t5memos/donaldpg.pdf>)

1 For the purposes of this document, "listed source categories" refer to the source categories identified in 40 CFR §§ 51.165(a)(1)(iv)(C), 51.166(b)(1)(iii), 52.21(b)(1)(iii), 52.24(f)(4)(iii), and the second definition of "major source" in 40 CFR 70.2 and 71.2.

2 Consistent with a voluntary remand in a case regarding the question of when is a source of fugitive emissions major for purposes of Title V, EPA has rescinded its interpretation of what the collocation language of 40 CFR part 70 requires with respect to unlisted sources of fugitive emissions. As explained in a memorandum from EPA, States have discretion in interpreting what the part 70 rule's collocation language requires with respect to unlisted sources of

fugitive emissions. Memorandum from Lydia Wegman to Regional Air Director (June 2, 1995) (<http://www.epa.gov/Region7/programs/artd/air/title5/t5memos/amcguide.pdf>). Please refer to this memorandum for an explanation of the scope of the voluntary remand. As a result of this voluntary remand, the first two scenarios discussed below may, or may not, be applicable to the implementation of part 70 in your State, depending on your State's exercise of its discretion.

3 This scenario is relevant for determining whether a source is a major source for purposes of section 112 and therefore Title V. (See first definition of "major source" in 40 CFR 70.2 and 71.2). The inclusion of fugitive emissions of HAPs in major source determinations is generally not relevant for PSD. The requirements of the PSD program do not apply to pollutants listed as HAPs under section 112(b) of the Act. See 42 U.S.C. § 7412(b)(6).



**AIR AND RADIATION DIVISION
77 WEST JACKSON BOULEVARD (A-18J)
CHICAGO, ILLINOIS 60604**

(800) 621-8431 or (312) 353-2212



[fugitives.covers.pdf](#) [fugitives.enclosure.pdf](#)

